

Aura STP Not working Data	
Category	Filter Feed Pump
S.No	1
Description of Issue	Fliter feed pumps are not working.
Root Cause	Both the pumps were engulfed in water due to the water flooding from the overflow line of Manjeera water tank.
Action Required / Planned	Sent to repair
Pending from days	39
Responsibility	APMS
Estimated Date of Completion	31.01.2019
Notified to the concerned	APMS (Working from 23.01.2019)