

Kanopy Tulip - Equipment Not Working Data	
Category	Booster Pumps
S.No	4
Description of Issue	Booster Pumps are in manual mode
Root Cause	J Block booster pump is in manual mode due to pressure switch failure and 5th floor residents are complaining that booster pump is creating vibration and noise to the flat just below the pump whenever it starts
Action Required/ Planned	-
Pending from days	5
Estimated Date of Completion	30.04.2019
Responsibility	Society
Notified to the concerned	Society