

Elina STP Not working Data	
Category	Hydro Pneumatic Pump
S.No	4
Description of Issue	One of the Hydro pneumatic pump had not worked for one day.
Root Cause	Problem with the Pressure transmitter switch.
Action Required / Planned	Problem was rectified by changing the pressure transmitter switch.
Pending from days	Completed
Responsibility	APMS
Notified to the concerned	APMS