

Parts List


2 ea. Reflective Sensors 2 ea. 3-pin headers



2 ea. Connecting Cable



2 ea. Mounting Plates



2 ea. #4-40 x 1/4" Panhead Machine Screw




2 ea. 10K 1/4W Resistor



Next, take one of the mounting plates, and thread the wires from one of the cables through the L-shaped slot. Insert the sensor's alignment pin into the mating mounting plate hole. Secure the sensor to the mounting plate with a screw; it will self-tap securely into the plate. Repeat for the other sensor, but with the opposite orientation. When finished you will have two mounted sensors that are mirrors of each other:



Using the servo screws removed in the first step, mount each sensor to the chassis so the lenses are near to the servo shaft. Do not tighten the screws yet. See photo:




Viewing the servos from the chassis bottom, adjust their positions so that their shafts align as closely as possible. Either center both in their respective cutouts, or push them both toward (not away from) the sensor connector. Just make sure they're the same. Now tighten all 8 servo screws.


The sensor cable may now be brought out from under the front of the printed circuit board and inserted into the prototyping area. The wires in the cable are assigned as follows:

Red: Vdd
Black: Vss
White: Signal (open collector)

The encoders should be wired according to the schematic on the next page. You can poke the 3-pin headers into the cable ends for insertion into the solderless breadboard. As an option, you can set the servo header jumper to Vdd (+5V, which would make the servos slower), plug the connectors into the P14/P15 servo headers, and add the pull-up resistors from the P14/P15 locations on connector X2 to Vdd. **Do not connect encoders to VIN.**



A typical implementation of this schematic is shown below:




Operation

The sensors emit infrared light and look for its return from a reflective surface. They are calibrated for optimal sensing of surfaces a few millimeters away. The Boe-Bot's wheels, even though they are black, reflect sufficient IR to cause the sensors to respond. When a sensor "sees" part of a wheel, it pulls its output low. When it's looking through a hole, its output floats, and the pullup resistor pulls it high.

Because the sensors emit and detect only modulated IR (at about 7.8 kHz) they are relatively insensitive to ambient light. Be aware, though, that some fluorescent fixtures may also emit light at this frequency and could interfere with their operation.

As a Boe-Bot wheel turns, the sensor will see an alternating pattern of hole - no hole - hole - no hole, etc. Its output will be a square wave whose frequency corresponds to the speed of rotation. If the Boe-Bot is rolling along the

floor, each edge of the square wave will mark an increment of travel slightly more than 1/2 inch (1.27 cm), as shown in the illustration below:



By tracking changes in the encoders' outputs, it's possible for a BASIC Stamp program to tell how far the Boe-Bot has traveled. Notice that the encoders themselves do not tell the program which direction the wheels are turning—only when and how far. But if the program is driving the wheel servos, it knows which direction each wheel is turning and can apply this additional information along with the encoder outputs. In the most sophisticated applications, it is possible not only to keep track of the Boe-Bot's position and direction, but also to coordinate the rotations of the two wheels, using the encoders as feedback, to obtain any desired motion contour.

Be aware, though, that wheel encoders are never perfect. Uncertainties in the effective wheel diameters can lead to position errors. Further uncertainties in effective wheel spacing during turns can result in direction errors. And even small position and direction errors have a way of accumulating quickly if not periodically corrected using external references. To obtain the best accuracy, always run on a hard, flat, smooth surface, such as a vinyl or hardwood floor—never on carpet.

The following sample program uses feedback from the encoders to traverse a star-shaped pattern on the floor. It is uncalibrated so is therefore unlikely to return exactly to its starting point. But try it anyway to see how close it gets. More complicated examples, including coordinated motion, X-Y position and direction odometry, calibration techniques, and the theory behind them, may be downloaded from www.parallax.com, just search "28107".

Assembly

To assemble the Boe-Bot Digital Encoder Kit, you will need a small Phillips screwdriver and a pair of needlenose pliers. Begin by removing both wheels from the Boe-Bot, and save the servo screws. Next, remove the top two screws holding each servo (the ones nearest the crease in the chassis). Loosen the remaining servo mounting screws:



Plug a connecting cable into each sensor, as shown:

