

## Grant Robinson

---

**From:** Mcconnell, DAVE P <dave.p.mcconnell@lmco.com>  
**Sent:** Monday, September 05, 2016 2:44 PM  
**To:** Grant Robinson  
**Subject:** S-76 MLG Drag Brace Support Crack Repair

Grant;

Following is the CSE response to my FTR requesting DRB repair and 8100-9's for five TAS S-76's.

Customer: Thai Aviation Services Limited  
Aircraft Serial Number: 760691  
Aircraft Model: S-76C++  
ATA: 32  
Part Number: 76204-02008-119 / -120  
Case Number: C0038857  
Title: MLG Drag Brace Support Bracket Crack-Request For DRB

### Issue Description:

TAS reports finding cracked MLG drag brace fitting support brackets on the below listed S-76C++ A/C.

A/C S/N 760691 A/C TT 9757.7 Landings 16400

A/C S/N 760693 A/C TT 10576.8 Landings 18992

A/C S/N 760697 A/C TT 11381.7 Landings 19689

A/C S/N 760720 A/C TT 11665.0 Landings 20553

A/C S/N 760724 A/C TT 11221.2 Landings 18650

Typical cracks and their locations are shown in the attached JPEG images. Note: Although A/C S/N 760724 is not represented in the close-up pictures, cracking appearances are identical to those represented for the other A/C.

TAS request:

- 1) SA approval to perform all repairs per DRB 2014-SA-76-005
  - 2) Signed FAA Form 8100-9 for each of the above listed A/C
- EoM

### Resolution:

Please check the Thai Aviation Services (Thailand) DocPak for DRB 2016-SA-76-034 MLG Drag Brace Support Brackets Cracked and the 5 ODA forms. If further assistance is required, please contact Service Engineering.

### David P. McConnell

Senior Field Service Representative  
Sikorsky, a Lockheed Martin company  
Email [dave.p.mcconnell@lmco.com](mailto:dave.p.mcconnell@lmco.com) NOTE NEW EMAIL ADDRESS  
Smartphone +1 (203) 873-8552 (US)  
Efax +1 (860) 998-8791 (US)  
Cell +66 (0)8 7750-7920 (Thailand)

