

Grant Robinson

From: McConnell, David P SIK <DMcConnell@SIKORSKY.COM>
Sent: Saturday, July 23, 2016 9:49 AM
To: Grant Robinson
Cc: Daryl Dixon; Daryl Balmer; Nakhon Supervisor Engineer
Subject: 920279 Broken HISL Light Lens

Grant:

For info and reference –

HISL light lens and gasket P/Ns as per the FTR response below,

Customer: Thai Aviation Services Limited
Aircraft Serial Number: 920279
Aircraft Model: S-92A
ATA: 33
Part Number: 2LA003849-26
Case Number: C0032306
Title: HISL Light Assembly-Request For Detail P/Ns

Issue Description:

Reference AMM Task 33-42-03-900-001 - Removal of High Intensity Strobe Lights

Please provide the P/Ns for the following detail parts of the P/N 2LA 003 849-26 High Intensity Strobe Light (HISL) assembly.

1. Strobe light lens cover
2. Strobe light lens cover gasket

Also, please note a typographical error in the IPC: P/N 2LS 003 849-26 is listed. The correct P/N is 2LA 003 849-26.

EoM

Resolution:

The lens part number is **9EL401888-00** and the gasket part number is **9GD401676-00**. (From Goodrich)

David P. McConnell

Senior Field Service Representative
Sikorsky, a Lockheed Martin company
Smartphone +1 (203) 873-8552 (US)
Efax +1 (860) 998-8791 (US)
Cell +66 (0)8 7750-7920 (Thailand)

