

Grant Robinson

From: Mcconnell, DAVE P <dave.p.mcconnell@lmco.com>
Sent: Monday, January 09, 2017 1:57 PM
To: Grant Robinson
Cc: Daryl Balmer; Russell Squires
Subject: S-76D Vent Fan ducting check

Grant;

Following is the CSE response to Russ's request for clarification of a conflict between the S-76D ETM and IETM.

Case Number: C0049154
Customer: Thai Aviation Services Limited
Aircraft S/N: 761XXX
Aircraft Model: S-76D
Part Number: 76309-77052-011
Case Subject: AMM Task 21-20-04-200-801-ETM IETM Conflict

Problem Description:

TAS notes a contradiction in inspection requirements between the IETM and ETM for task 21-20-04-200-801.

The IETM and ETM AWL for S76D both have the following 1500 hour inspection.

TASK 5-20-00-200-008
1500-Hour Inspection Checklist Zone 1
Vent fan ducting (If installed) 21-20-04-200-801

S-76D ETM PDF version of AMM chapter 21 states the following:

TASK 21-20-04-200-801

1500 Hour Inspection Sound Suppressor.

SUBTASK 21-20-04-210-001

Inspect Sound Suppressor

With qualified helicopter pilot at controls, start engines. (Refer to Approved Rotorcraft Flight Manual, SA S76D-RFM-000.)

With cabin heater on, inspect sound suppressor in the baggage compartment for cracks/leaks and repair/replace as necessary.

With qualified helicopter pilot at controls, shut down engines. (Refer to Approved Rotorcraft Flight Manual, SA S76D-RFM-000.)

S76D IETM for the same TASK 21-20-04-200-801 is as follows:

TASK 21-20-04-210-001

1500 Hour Inspection Vent Fan Ducting.

SUBTASK 21-20-04-210-001

Inspect Vent Fan Ducting.

Open baggage compartment door. (Refer to Removal/Installation, TASK 52-30-01-900-801.)

Perform ventilation mode test. (Refer to Testing and Troubleshooting, SUBTASK 21-40-00-710-001.)
Inspect vent fan ducting for cracks/leaks replace as necessary. (Refer to Removal/Installation.)
Close baggage compartment door. (Refer to Removal/Installation, TASK 52-30-01-900-801.)

Please advise which AMM document - ETM or IETM - is correct. EoM

Problem Resolution:

Maintenance Planning has confirmed that the ETM PDF version of the task should be followed.

The IETM will be updated during the next scheduled revision.

David P. McConnell

Senior Field Service Representative
Sikorsky, a Lockheed Martin company
Email dave.p.mcconnell@lmco.com
Smartphone +1 (203) 873-8552 (US)
Efax +1 (860) 998-8791 (US)
Cell +66 (0)8 7750-7920 (Thailand)



WARNING: THE INFORMATION IN THIS TRANSMISSION IS CONFIDENTIAL AND IS MEANT TO BE READ AND USED ONLY BY THE INTENDED RECIPIENT. ENCLOSED COMMODITIES, TECHNICAL DATA OR SOFTWARE ARE SUBJECT TO THE EXPORT CONTROL OF EITHER THE INTERNATIONAL TRAFFIC IN ARMS REGULATIONS (ITAR) OR THE EXPORT ADMINISTRATION REGULATIONS (EAR) AND CANNOT BE EXPORTED WITHOUT THE AUTHORIZATION OF EITHER THE DEPARTMENT OF STATE OR THE DEPARTMENT OF COMMERCE PRIOR TO EXPORT. EXPORT INCLUDES DISCLOSURE AND OR ACCESS TO COMMODITIES, TECHNICAL DATA OR SOFTWARE BY FOREIGN NATIONALS WHETHER LOCATED IN THE UNITED STATES OR ABROAD. THIS REQUIREMENT APPLIES EQUALLY TO FOREIGN NATIONAL EMPLOYEES OF U.S. COMPANIES AND THEIR FOREIGN SUBSIDIARIES. THIS DOCUMENT, OR AN EMBODIMENT OF IT IN ANY MEDIA, DISCLOSES INFORMATION WHICH IS PROPRIETARY, IS THE PROPERTY OF SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES, IS AN UNPUBLISHED WORK PROTECTED UNDER APPLICABLE COPYRIGHT LAWS, AND IS DELIVERED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED, DISCLOSED, REPRODUCED, IN WHOLE OR IN PART (INCLUDING REPRODUCTION AS A DERIVATIVE WORK), OR USED FOR MANUFACTURE FOR ANYONE OTHER THAN SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES WITHOUT ITS WRITTEN CONSENT, AND THAT NO RIGHT IS GRANTED TO DISCLOSE OR SO USE ANY INFORMATION CONTAINED HEREIN. ALL RIGHTS RESERVED. ANY ACT IN VIOLATION OF APPLICABLE LAW MAY RESULT IN CIVIL AND CRIMINAL PENALTIES. ANY REVIEW, USE, DISSEMINATION, DISTRIBUTION OR COPYING OF THIS TRANSMITTAL BY AN UNINTENDED RECIPIENT IS STRICTLY PROHIBITED, AND MAY BE A VIOLATION OF LAW SUBJECT TO PENALTY.