

## Thanakom Panyothin

---

**From:** Mcconnell, DAVE P <dave.p.mcconnell@lmco.com>  
**Sent:** Wednesday, July 11, 2018 11:20 AM  
**To:** Grant Robinson; Thanakom Panyothin  
**Subject:** RE: HTN

Grant

This from a Case dated 28 JUN 2018 in response to another field rep:

Aircraft Model: S-76C++  
Submitted On: 6/28/2018 9:24 AM  
Case Subject: MLG drag brace bolt bushing interchangeability

### Issue Description:

The customer is looking for the bearings MS21241-12-C014 and C018 which are used for landing gear drag brace bolt installation. SCI has no stock, but they would like Sikorsky to advise if the following parts are able to be alternate parts.

Bearings

P/N MS21241-12-C014, (IPC Chap 32-10-01 Fig 1-12) = M81934/2-12C014

P/N MS21241-12-C018, (IPC Chap 32-10-01 Fig 1-13) = M81934/2-12C018

This email notification is provided as the case has been reviewed and does not contain technical data in the issue description.

### Problem Resolution:

Per the Sikorsky engineering parts database (Matrix-one), the following information applies:

MS21241-12-C014 is superseded by M81934/2-12C014

MS21241-12-C018 is superseded by M81934/2-12C018

Soundoff DAP-C0098264 has been submitted to have the IPC updated.

This email notification is provided as the case has been reviewed and does not contain technical data in the resolution.

---

**From:** Grant Robinson <Grant\_r@tasl.co.th>  
**Sent:** Wednesday, July 11, 2018 10:40  
**To:** Mcconnell, DAVE P (TH) <dave.p.mcconnell@lmco.com>; Thanakom Panyothin <thanakom\_p@tasl.co.th>  
**Subject:** EXTERNAL: FW: HTN

Below from H1

Best Regards,

Grant Robinson  
Repair Station Manager

Thai Aviation Services Ltd.