



Phil's Body Shop
2955 160th St. W. Rosemount MN
55068
Telephone:
Email:Info@philsautobody.com

Vehicle Diagnostic Report

2021 CHEVROLET Silverado
VIN:1GC5YSE79MF289804
Engine Size:L8T 6.6L 8
Odometer:23,800 miles
License #:22042

Report Type:Pre-Repair
Found codes in 3 of 15 systems
Test Time:2024-02-19 03:34:35 PM
Technician Name:21979



System fault code

System Name	Status	Description
Engine Control Module (ECM)	0 Code	
Chassis Control Module - Auxiliary (CCMA)	0 Code	
Transmission Control Module (TCM)	0 Code	
Transfer Case Control Module (TCCM)	0 Code	
Electronic Brake Control Module (EBCM)	1 Code	1.U0422-00: Invalid Data Received From Body Control Module
Steering Wheel Angle Sensor Module (SWASM)	0 Code	1.C0760-29: Left Rear Tire Pressure Sensor - Too Few Pulses
Body Control Module (BCM)	1 Code	
Serial Data Gateway Module - Processor 1 (SDGM_P1)	0 Code	
Serial Data Gateway Module - Processor 2 (SDGM_P2)	0 Code	
Inflatable Restraint Sensing And Diagnostic Module (IRSDM)	0 Code	
Passenger Presence Module (PPM)	0 Code	
Instrument Cluster (IC)	0 Code	
Heating Ventilation And Air Conditioning Controls (HVACC)	0 Code	
Radio (RADIO)	1 Code	1.B124B-00: Universal Serial Bus (USB) Circuit 1
Heating Ventilation And Air Conditioning Control Module (HVACCM)	0 Code	