

FUJIKURA FIBER OPTICS VIETNAM
RETURN PRODUCT CONFIRMATION

Form: 5-PR-011-5-Fo-0001	Version: 01	Page: 1/1
Record no : 5-PR-011-5-Fo-0001-9-RC-0002	Record name: Returned product AGG0013	
Prepared by: HangVT	Date: 4-Oct-24	

1. Returned product information

Product code: AGG0013 Product name: GLACIER FIBER ARRAY (80UM)
 PO no: FPO230012840-2, FPO230012840-3, FPO230012840-4 Quantity: 422pcs

Product code	PO no.	Quantity
AGG0013	FPO230012840-2	22
AGG0013	FPO230012840-3	200
AGG0013	FPO230012840-4	200

Reason of returning: Epoxy attached on fiber

2. Receipt confirmation

Agreement Number: AG-FOV-CNCC-2408-007

2.1 Check and confirm with Agreement: ☐ OK ☒ NG


Remark: The quantity according to each PO is different with the agreement
 There are 2pcs AGG0015 mixed with AGG0013

Product code	PO no.	Quantity
AGG0013	FPO230012840-1	145
AGG0013	FPO230012840-2	5
AGG0013	FPO230012840-3	185
AGG0013	FPO230012840-4	10
AGG0013	FPO230012840-5	75
AGG0015	FPO230012840-6	2


Reciever: HangVT
 Date: September 25, 2024

2.2 Phenomenon confirmation ☐ OK ☒ NG


Remark: Product had quite bad packing condition: fiber bend, connector jump out, connector touch fiber, sponge was inserted in a messy way



Fiber bend, sponge was inserted in a messy way



Connector jump out, sponge was inserted in a messy way



Connector press on fiber

Checked by: HangVT
 Date: September 25, 2024

3. Treatment instruction

Solution: Re-inspect and clean fiber follow 9-WI-003-9-FO-001-9-RC-1291
 PIC: SV and leader PRD Acacia line

Instructed by (Engineer up): HangVT
 Date: October 1, 2024

4. Rework result confirmation

Confirmed by: HangVT
 Date: October 4, 2024

Checked by: *Phu Mai*
 Date: 04 Oct 24

☒ OK ☐ NG

5. Shipment Approval

☒ Approve ☐ Reject

Reason:

Action need to do next:

Approved by: *Phu*
 Date: 4 Oct 24 *B. Tran*

"Confidential"

"FOV's property, do not take out without FOV BOM's approval."