

existing site conditions

The existing site topography condition has all runoff go out of the site. There are no swales located on site however there is a pond. Existing tree line to the north acts as a buffer zone to neighborhood, but is too dense to not allow traffic to have a view into the site. Dense evergreen forest to the east can offer wind protection on site. Entrance to the site is located at a highpoint on the site.

