


BOM CHANGE NOTICE

1. BCN No.- 03
Proj. BCN. - 01

2. BCN Category (make one)		3. Originator's Name, Organization Telephone No.-		4. Department:-		5. Date-02.03.2018	
As per ECN	<input type="radio"/>	BAHUBALI		DESIGN	<input checked="" type="radio"/>	6. Item code :- JTO0271718	
Temporary	<input type="radio"/>			PURCHASE	<input type="radio"/>		
Design Improvement	<input type="radio"/>			PRODUCTION	<input type="radio"/>		
Sales-Cus. Requirement Change	<input type="radio"/>			STORE	<input type="radio"/>		
Production- suggestion/changes	<input type="radio"/>	7. Project Title / No./ Work Order No. C.O. JTO027_1718		QUALITY	<input type="radio"/>	9. Design Authority Sign & Date.	
Purchase- Non availability	<input type="radio"/>			8. Modification Work completed.	<input checked="" type="radio"/>	Date. 02/03/2018	
After Sales -Required	<input checked="" type="radio"/>			Yes- <input checked="" type="radio"/> No- <input type="radio"/>			
Design Error	<input type="radio"/>						
Description of Changes.							
REOPEN MAIN FINISH GOOD CODE-JTO027_1718							
REASON - STD-30 HOIST JOINING PLATE BOLT BREAKAGE DUE TO HIGH LOAD							
SOLUTION - PLATE MODIFICATION WITH DOWEL HOLE							
11. Distribution (include name, no.. Of copies)						12. Department Authority sign & Date .	
PRODUCTION--							
PURCHASE --							
QUALITY--							
STORE--						 02/03/2018	