

Sr. No	Month	Customer Name	CO Number	Rework	Description	Department
66	Jan-18	ABB INDIA LIMITED	A25J028_1718	Jib crane is vibrating	System replacement need to be done	Design
67	Jan-18	ABB INDIA LIMITED	A36O069_1718	Structure is vibrating	Structure modification requiried	Design
68	Jan-18	TYCHE CAST TECH PVT. LTD.	T37K018_1718	lot of reworks at site	Reworks at site	MGF / Quality
69	Jan-18	Amara Raja Battreies LTD	A35K032_1718	Short supply of chemical boltes	resent at site	Design
70	Jan-18	SML ISUZU LIMITED	S73O048_1718	Poor quality of paint	repaint at site	MGF / Quality
71	Jan-18	JCB India Ltd	JGJ030_1718	wrong supply of hardwares	resent at site	MGF / Quality
72	Feb-18	Raptech Engineering Pvt. Ltd.	R1K043_1718	Short supply For Bus Bar Bracket, End Stopper.	short supply	Dispatch
73	Feb-18	Tata Toyo	T38K038_1718	wrong supply	Motor Mouting Palate	MGF / Quality
74	Feb-18	A K STEELS	A46K028_1718	Current collector bracket, Main panel location	modification at site	Design
75	Feb-18	VIGEL MANUFACTURING	VHK041_1718	Hoist installation pending	Old hoist replace by new hosit	NA