

Inspection Before Coating Removal

Existing Coating

Coating Type : Extruded Epoxy

Repair Length : 38.00 m

Field Join Type : F001

wather condense : 1.00


Coating Thickness : 3.00 μm

Holiday Test : 3.00

Coating damage mapping



38.00(m)



Picture: Overall Coating Damaged

Picture: Overall Coating Damaged

Grith Weld Position (Distance from U/S) 28 m

Seam Weld Position (Degree Position) :

Item	Defect Type	Dimension(mm)		Distance from U/S (m)	Degree Position (c)	Risk Score	Remark	File
		Width	Length					
1	Blister	2.00	12.00	3.00	180.00	1	11111	
2	Crack	2.00	15.20	4.00	90.00	3	2222222	
3	Gouge	3.00	29.80	.00	.00	5	3333333	

Defect Type:

1.Crack

4.Chalk

2.Pin hole

5.Discoloration

3.Blister

6.Gouge

Risk score				
1	2	3	4	5



Degree of Coating

condition (Follow Flow

Direction)