

Lerdge X Pin Map

MOTOR											
X AXIS	EN	PB11	Y-AXIS	EN	PB1	Z-AXIS	EN	PC4	E-AXIS	EN	PA5
	STEP	PB10		STEP	PB0		STEP	PA7		STEP	PA4
	DIR	PB2		DIR	PC5		DIR	PA6		DIR	PA3

ENDSTOP					
X-ENDSTOP	PB12	Y-ENDSTOP	PB13	Z-ENDSTOP	PB14

TEMPERATURE SENSOR			
HOTEND SENSOR	PC0	*HOTBED SENSOR	PC1

HEATER			
HOTEND HEATER	PA1	*HOTBED HEATER	PA2

FAN			
HOTEND SINK FAN	PC15	COOLING FAN	PA0

LED			
WHITE LED	PC6	STATUS LED	PC7

FILAMENT SWITCH SENSOR	
EXTRUDER0	PE1

OTHER					
PROBE	PB15	SERVO	PD13	AUTO POWER	PC14

Note: Pins marked with * require expansion modules