

Example Report



Company	Thermal Specialists of Conway LLC 3180 Cresthaven Conway AR	Tester: Thomas Epperson Phone: 501-733-7390 E-Mail: thomas.epperson@gmail.com
----------------	--	--

Device	testo 875-2	Serial No.: 1840576
---------------	-------------	---------------------

Customer	Jim Doyle 1305 Grape Jelly Ave Chair, NM	Measuring Site: 1305 Grape Jelly Ave Char, NM
-----------------	--	---

Task




Example Report

File:
DUCTCEILING.BMT

Date:
7/14/2010

Measuring Time:
6:23:50 PM



Picture parameters:

Emissivity: 0.95
Refl. temp. [°F]: 68.0

Remarks:

Insulation missing in ceiling near new duct-work. The duct-work in question is located in the living room. Insulation should be placed in this area to reduce energy losses.




Example Report

File:
DUCTATTIC.BMT

Date:
8/13/2010

Measuring Time:
8:43:09 AM



Picture parameters:

Emissivity: 0.95
Refl. temp. [°F]: 68.0

Remarks:

Insulation missing around air ducts allowing cold air to flow into the hot attic.




Example Report

File:
DUCTJOINT.BMT

Date:
7/11/2010

Measuring Time:
7:02:34 PM



Picture parameters:

Emissivity: 0.95
Refl. temp. [°F]: 68.0

Remarks:

This particular branch of the duct work is missing insulation at the joint. The metal duct is visible at the joint instead of being covered with insulation.





Example Report

File:
DOORJAMB.BMT

Date:
7/11/2010

Measuring Time:
6:24:20 PM



Picture parameters:

Emissivity: 0.95
Refl. temp. [°F]: 68.0

Remarks:

This energy leak is caused by a worn door jamb seal.





Example Report

File:
CABLEATTIC.BMT

Date:
7/11/2010

Measuring Time:
7:03:12 PM



Picture parameters:

Emissivity: 0.95

Refl. temp. [°F]: 68.0

Remarks:

Thin spots in the insulation where a cable had been run across the attic floor and the insulation had been disturbed.

Review:

This is a sample report. It contains some of the things that can be found on a typical thermal inspection of your home. If you are ready to schedule an inspection for your home or place of business please e-mail us at contact@thermalspecialist.com to have an inspection scheduled. You can also call us at 501-733-7390, be sure to ask for Thomas.

2/22/2011 ,

Thomas Epperson