

ASBESTOS REGISTER

SITE: 7740 Douglas 44 Becky Avenue, North Rocks

LAST UPDATED: 03/11/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Type	Friable / Non-Friable	Quantity	Condition	Assessment / Action
09/01/2017	Eave soffit lining	Asbestos cement sheet	Non-friable	30 sqm	Good/stable Painted	Protect the retained ACM from damage during the course of the works
09/01/2017	Gable end cladding	Asbestos cement sheet	Non-friable	3 sqm	Good/stable Painted	Protect the retained ACM from damage during the course of the works
09/01/2017	Entry wall	Asbestos cement sheet	Non-friable	5.2 sqm	Good/stable Painted	Demolish and remove as part of the contract works
09/01/2017	WC wall lining	Asbestos cement sheet	Non-friable	7.2 sqm	Good/stable Painted	Protect the retained ACM from damage during the course of the works
09/01/2017	Bathroom wall lining	Asbestos cement sheet	Non-friable	17.5 sqm	Good/stable Painted	6.5 sqm to be removed as part of the contract works, protect the retained ACM from damage during the course of the works

ASBESTOS REGISTER

09/01/2017	WIR flooring	Asbestos cement sheet	Non-friable	3 sqm	Good/stable Not sealed	Protect the retained ACM from damage during the course of the works
09/01/2017	Disused ceiling mounted HWS	ACM	Non-friable	Unknown	Unknown	Remove and dispose of the disused hot water system
09/01/2017	Electrical meter board	ACM	Non-friable	0.25 sqm	Good/stable	Protect the retained ACM from damage during the course of the works
09/01/2017	Under floor space (South Eastern corner)	Asbestos cement sheet	Non-friable	Unknown	Broken pieces/damaged	Remove and dispose of the ACM
09/01/2017	Garage	Asbestos cement sheet	Non-friable	Unknown	Good/Stable	25 sqm removed 03/11/2017