

ASBESTOS REGISTER

SITE: 7816 Pacque 30 Highfield Road, Lindfield

LAST UPDATED: 22/06/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Type	Friable / Non-Friable	Quantity	Condition	Assessment / Action
14/06/2017	Hot water unit flue pipe (rear balcony)	Asbestos cement	Non-friable	1 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
14/06/2017	Bedroom 1 WIR ceiling	Asbestos cement sheet	Non-friable	1 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
14/06/2017	Bedroom 2 WIR ceiling	Asbestos cement sheet	Non-friable	1 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
14/06/2017	Bedroom 3 WIR ceiling and wall	Asbestos cement sheet	Non-friable	4 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
14/06/2017	Void – shelving and rear wall	Asbestos cement sheet	Non-friable	3 sqm	Good/Stable	Protect the retained ACM from damage during the course of the works

ASBESTOS REGISTER

14/06/2017	Electrical meter board	ACM	Non-friable	0.25 sqm	Good/Stable	Protect the retained ACM from damage during the course of the works
------------	------------------------	-----	-------------	----------	-------------	---