

ASBESTOS REGISTER

SITE: 7853 Burge 4 Allars Street, Denistone West

LAST UPDATED: 12/09/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Type	Friable / Non-Friable	Quantity	Condition	Assessment / Action
08/09/2017	Eave soffit lining	Asbestos cement sheet	Non-friable	19 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
08/09/2017	Front porch ceiling lining	Asbestos cement sheet	Non-friable	1 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
08/09/2017	Side porch ceiling lining	Asbestos cement sheet	Non-friable	1 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
08/09/2017	Garage ceiling lining	Asbestos cement sheet	Non-friable	22 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
08/09/2017	Laundry wall and ceiling lining	Asbestos cement sheet	Non-friable	4 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works

ASBESTOS REGISTER

08/09/2017	WC ceiling lining	Asbestos cement sheet	Non-friable	1 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
08/09/2017	WC floor covering	Asbestos cement sheet	Non-friable	1 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
08/09/2017	Disused ceiling mounted hot water system	Asbestos cement sheet	Non-friable	Unknown	Unknown	Remove and dispose of the disused hot water system with ACM
08/09/2017	Electrical meter board	Asbestos cement sheet	Non-friable	0.25 sqm	Good/Stable	Protect the retained ACM from damage during the course of the works
08/09/2017	Under floor space	Asbestos cement sheet	Non-friable	Unknown	Broken pieces Damaged	Remove and dispose of the ACM