

# ASBESTOS REGISTER

**SITE:** 7799 Hoare.Willemsen 15 Allison Avenue, Lane Cove

**LAST UPDATED:** 24/10/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Type	Friable / Non-Friable	Quantity	Condition	Assessment / Action
06/06/2017	Eave soffit lining	Asbestos cement sheet	Non-friable	3.5 sqm	Good/Stable Painted	Protect the retained ACM from damage during the course of the works
06/06/2017	Weatherboard cladding (outside kitchen)	Asbestos cement sheet	Non-friable	0.5 sqm	Good/Stable Painted	To be removed by Cape Cod as part of the contract works
06/06/2017	Gable end cladding	Asbestos cement sheet	Non-friable	22 sqm	Good/Stable Painted	18 sqm to be removed by Cape Cod as part of the contract works. Protect the retained ACM from damage during the course of the works
06/06/2017	Front porch soffit lining and ceiling end lining	Asbestos cement sheet	Non-friable	0 sqm	Good/Stable Painted	Removed by Cape Cod 21/10/2017

## ASBESTOS REGISTER

06/06/2017	Spandrel panels (lounge and bedroom 4) internal and external	Asbestos cement sheet	Non-friable	3 sqm	Good/Stable Painted	Protect the retained ACM from damage during the course of the works
06/06/2017	Stairwell wall lining	Asbestos cement sheet	Non-friable	2.5 sqm	Good/Stable Painted	Protect the retained ACM from damage during the course of the works
06/06/2017	Rumpus room ceiling lining	Asbestos cement sheet cladding	Non-friable	12 sqm	Good/Stable Painted	Protect the retained ACM from damage during the course of the works
06/06/2017	Laundry ceiling lining	Asbestos cement sheet cladding	Non-friable	2 sqm	Good/Stable Painted	Protect the retained ACM from damage during the course of the works
06/06/2017	Disused ceiling mounted hot water system	ACM	Non-friable	Unknown	Unknown	Remove and dispose of the ACM as part of the contract works