

ASBESTOS REGISTER

SITE: 7804 Zhu.Zhang 167A Carlingford Road, Epping

LAST UPDATED: 01/05/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Type	Friable / Non-Friable	Quantity	Condition	Assessment / Action
27/04/2017	Eave soffit lining	Asbestos cement sheet	Non-friable	24.75 sqm	Good/stable Painted	16 sqm to be removed as part of the contract works. Protect the retained ACM from damage during the course of the works
27/04/2017	Garage eave soffit lining	Asbestos cement sheet	Non-friable	10.8 sqm	Good/stable Painted	Remove and dispose of the ACM as part of the contract works
27/04/2017	Front porch soffit lining	Asbestos cement sheet	Non-friable	4.5 sqm	Good/stable Painted	Protect the retained ACM from damage during the course of the works
27/04/2017	Shower room 1 ceiling lining	Asbestos cement sheet	Non-friable	16.8 sqm	Good/stable Painted	Protect the retained ACM from damage during the course of the works
27/04/2017	Electrical meter board	ACM	Non-friable	0.25 sqm	Good/stable	Protect the retained ACM from damage during the course of the works