

ASBESTOS REGISTER

SITE: 7813 Jones.Critchard-Jones 23 Bay Street, Botany

LAST UPDATED: 21/11/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Type	Friable / Non-Friable	Quantity	Condition	Assessment / Action
03/05/2017	External wall cladding	Asbestos cement weatherboards	Non-friable	86.5 sqm	Good/stable Painted	Protect the retained ACM from damage during the course of the works
03/05/2017	Eave soffit lining (under front gables)	Asbestos cement sheet	Non-friable	Nil	Good/stable Painted	2 sqm removed 21/11/2017
03/05/2017	Gable end cladding	Asbestos cement weatherboards	Non-friable	5 sqm	Good/stable Painted	Remove and dispose of the ACM as part of the contract works
03/05/2017	Front verandah side lining	Asbestos cement sheet	Non-friable	2.5 sqm	Good/stable Painted	Protect the retained ACM from damage during the course of the works
03/05/2017	Front verandah soffit lining	Asbestos cement sheet	Non-friable	7.5 sqm	Good/stable Painted	Protect the retained ACM from damage during the course of the works
03/05/2017	WC wall and ceiling lining	Asbestos cement sheet	Non-friable	8.5 sqm	Good/stable Painted	Protect the retained ACM from damage during the course of the works

ASBESTOS REGISTER

03/05/2017	Sun room wall and ceiling lining	Asbestos cement sheet	Non-friable	17.5 sqm	Good/stable Painted	Protect the retained ACM from damage during the course of the works
03/05/2017	Laundry/bathroom wall and ceiling lining	Asbestos cement sheet	Non-friable	40 sqm	Good/stable Painted	Protect the retained ACM from damage during the course of the works
03/05/2017	Electrical meter board	Asbestos cement weatherboards	Non-friable	0.25 sqm	Good/stable	Protect the retained ACM from damage during the course of the works