

# ASBESTOS REGISTER

**SITE:** 7896 McEwan 53 Wallalong Crescent, West Pymble

**LAST UPDATED:** 18/12/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Type	Friable / Non-Friable	Quantity	Condition	Assessment / Action
12/12/2017	Eave soffit lining	Asbestos cement sheet	Non-friable	23.5 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
12/12/2017	Garage gable end cladding	Asbestos cement sheet	Non-friable	5.5 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
12/12/2017	Front porch soffit lining	Asbestos cement sheet	Non-friable	1 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
12/12/2017	Laundry wall lining	Asbestos cement sheet	Non-friable	7.5 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
12/12/2017	Bathroom wall lining	Asbestos cement sheet	Non-friable	9.5 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works

## ASBESTOS REGISTER

12/12/2017	Ensuite wall lining	Asbestos cement sheet	Non-friable	22 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
12/12/2017	Garage ceiling lining	Asbestos cement sheet	Non-friable	40 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
12/12/2017	Electrical meter board	ACM	Non-friable	0.5 sqm	Good/Stable	Protect the retained ACM from damage during the course of the works