

# ASBESTOS REGISTER

**SITE:** 7866 Rigney 1 Carranya Road, Riverview

**LAST UPDATED:** 06/12/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Type	Friable / Non-Friable	Quantity	Condition	Assessment / Action
05/12/2017	Eave soffit lining	Asbestos cement sheet	Non-friable	37 sqm	Good/Stable Surface coated to the exposed areas	5 sqm to be removed by Cape Cod as part of the contract works  Protect the retained ACM from damage during the course of the works
05/12/2017	Laundry ceiling lining	Asbestos cement sheet	Non-friable	4 sqm	Good/Stable Surface coated to the exposed areas	To be removed by Cape Cod as part of the contract works
05/12/2017	WC ceiling lining (ground floor)	Asbestos cement sheet	Non-friable	2 sqm	Good/Stable Surface coated to the exposed areas	To be removed by Cape Cod as part of the contract works
05/12/2017	WC wall lining (first floor)	Asbestos cement sheet	Non-friable	2.5 sqm	Good/Stable Surface coated to the exposed areas	To be removed by Cape Cod as part of the contract works

## ASBESTOS REGISTER

05/12/2017	Bathroom wall lining (first floor)	Asbestos cement sheet	Non-friable	5 sqm	Good/Stable Surface coated to the exposed areas	To be removed by Cape Cod as part of the contract works
05/12/2017	Disused ceiling mounted hot water system	ACM	Non-friable	Unknown	Unknown	Remove and dispose of the disused hot water system with ACM