

ASBESTOS REGISTER



SITE: 7845 Tamas 1 Mocatta Avenue, Pymble

LAST UPDATED: 20/10/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Type	Friable / Non-Friable	Quantity	Condition	Assessment / Action
17/10/2017	Eave soffit lining	Asbestos cement sheet	Non-friable	26 sqm	Good/Stable Surface coated to the exposed areas	To be removed by Cape Cod as part of the contract works
17/10/2017	Rear patio soffit lining	Asbestos cement sheet	Non-friable	6.5 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
17/10/2017	Lounge, playroom and dining floor covering	ACM in parquetry flooring adhesive	Non-friable	Unknown	Unknown	Remove and dispose of the flooring with ACM
17/10/2017	Kitchen and laundry floor covering	ACM in linoleum base and adhesive	Non-friable	3 sqm	Good/Stable	Remove and dispose of the flooring with ACM
17/10/2017	Laundry ceiling lining	Asbestos cement sheet	Non-friable	4.5 sqm	Good/Stable Surface coated to the exposed areas	To be removed by Cape Cod as part of the contract works

ASBESTOS REGISTER

17/10/2017	Disused ceiling mounted hot water system	ACM	Non-friable	Unknown	Unknown	Remove and dispose of the disused hot water system with ACM
17/10/2017	Malthoid sarking to underside roof tiles	ACM	Non-friable	160 sqm	Good/Stable	Remove and dispose of the ACM
17/10/2017	Electrical meter board	ACM	Non-friable	0.25 sqm	Good/Stable	Protect the retained ACM from damage during the course of the works
17/10/2017	Laundry ceiling lining	Asbestos cement sheet	Non-friable	18 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
17/10/2017	Workshop under garage wall	Asbestos cement	Non-friable	4.5 sqm	Good/Stable	Protect the retained ACM from damage during the course of the works