

ASBESTOS REGISTER

SITE: 7860 Barnes 18 Panorama Road, Lane Cove

LAST UPDATED: 18/12/2017

JOB NUMBER CLIENT ADDRESS

| Date Identified | Location of ACM | Type | Friable / Non-Friable | Quantity | Condition | Assessment / Action |
|-----------------|---|-----------------------|-----------------------|----------|--|---|
| 14/12/2017 | Eave soffit lining | Asbestos cement sheet | Non-friable | 35.5 sqm | Good/Stable Surface coated to the exposed areas | 19 sqm to be removed by Cape Cod as part of the contract works Protect the retained ACM from damage during the course of the works |
| 14/12/2017 | Gable end cladding behind vinyl weatherboards | Asbestos cement sheet | Non-friable | 21.5 sqm | Good/Stable Surface coated to the exposed areas | 15 sqm to be removed by Cape Cod as part of the contract works Protect the retained ACM from damage during the course of the works |
| 14/12/2017 | Verandah soffit lining | Asbestos cement sheet | Non-friable | 10.5 sqm | Good/Stable Surface coated to the exposed areas | 6 sqm to be removed by Cape Cod as part of the contract works Protect the retained ACM from damage during the course of the works |

ASBESTOS REGISTER

| | | | | | | |
|------------|--|--------------------------------|-------------|---------|--|---|
| 14/12/2017 | Roof access cover | Asbestos cement sheet | Non-friable | 0.5 sqm | Good/Stable Surface coated to the exposed areas | To be removed by Cape Cod as part of the contract works |
| 14/12/2017 | Carport privacy wall | Asbestos cement sheet cladding | Non-friable | 7.5 sqm | Good/Stable Surface coated to the exposed areas | To be removed by Cape Cod as part of the contract works |
| 14/12/2017 | Electrical meter board | ACM | Non-friable | 0.5 sqm | Good/Stable Surface coated to the exposed areas | Protect the retained ACM from damage during the course of the works |
| 14/12/2017 | Disused ceiling mounted hot water system | ACM | Non-friable | Unknown | Unknown | Remove and dispose of the disused hot water system with ACM |