

ASBESTOS REGISTER

SITE: 7894 Shrestha.Bishwakarma 44 Woodville Road, Granville

LAST UPDATED: 07/12/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Type	Friable / Non-Friable	Quantity	Condition	Assessment / Action
05/12/2017	Eave soffit lining	Asbestos cement sheet	Non-friable	20.5 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
05/12/2017	Shower/laundry wall lining	Asbestos cement sheet	Non-friable	11.5 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
05/12/2017	Ensuite/laundry wall lining	Asbestos cement sheet	Non-friable	22 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
05/12/2017	Disused ceiling mounted hot water system	ACM	Non-friable	Unknown	Unknown	Remove and dispose of the disused hot water system with ACM
05/12/2017	Electrical meter board	ACM	Non-friable	0.5 sqm	Good/Stable	Protect the retained ACM from damage during the course of the works