

ASBESTOS REGISTER

SITE: 7826 Sacks 1 Dudley Road, Rose Bay

LAST UPDATED: 07/09/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Type	Friable / Non-Friable	Quantity	Condition	Assessment / Action
04/09/2017	Eave soffit lining	Asbestos cement sheet	Non-friable	4 sqm	Good/Stable Surface coated to the exposed areas	To be removed by Cape Cod as part of the contract works
04/09/2017	Gable end cladding	Asbestos cement sheet	Non-friable	12.5 sqm	Good/Stable Surface coated to the exposed areas	To be removed by Cape Cod as part of the contract works
04/09/2017	Hot water unit shed cladding	Asbestos cement sheet	Non-friable	11 sqm	Good/Stable Surface coated to the exposed areas	To be removed by Cape Cod as part of the contract works
04/09/2017	Front porch soffit lining	Asbestos cement sheet	Non-friable	4.5 sqm	Good/Stable Surface coated to the exposed areas	To be removed by Cape Cod as part of the contract works
04/09/2017	Sunroom/study ceiling lining	Asbestos cement sheet	Non-friable	6 sqm	Good/Stable Surface coated to the exposed areas	To be removed by Cape Cod as part of the contract works

ASBESTOS REGISTER

04/09/2017	Laundry ceiling and wall lining	Asbestos cement sheet	Non-friable	5.5 sqm	Good/Stable Surface coated to the exposed areas	To be removed by Cape Cod as part of the contract works
04/09/2017	WC/shower wall lining	Tilux sheeting ACM	Non-friable	5 sqm	Good/Stable Surface coated to the exposed areas	To be removed by Cape Cod as part of the contract works
04/09/2017	Malthoid sarking to underside roof tiles	ACM	Non-friable	Unknown	Good/Stable	Remove and dispose of the ACM