

ASBESTOS REGISTER

SITE: 7862 Hudson 24 Morella Road, Mosman

LAST UPDATED: 07/09/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Type	Friable / Non-Friable	Quantity	Condition	Assessment / Action
05/09/2017	Eave soffit lining	Asbestos cement sheet	Non-friable	21.5 sqm	Good/Stable Surface coated to the exposed areas	2.5 sqm to be removed by Cape Cod as part of the contract works Protect the retained ACM from damage during the course of the works
05/09/2017	Front porch soffit lining	Asbestos cement sheet	Non-friable	1.5 sqm	Good/Stable	Protect the retained ACM from damage during the course of the works
05/09/2017	Lower balcony fascia trim	Asbestos cement sheet	Non-friable	3.5 sqm	Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
05/09/2017	Upper balcony dwarf wall and soffit lining	Asbestos cement sheet	Non-friable	8.5 sqm	Good/Stable	Protect the retained ACM from damage during the course of the works

ASBESTOS REGISTER

05/09/2017	Laundry wall lining	Asbestos cement sheet	Non-friable	4 sqm	Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
05/09/2017	Cellar wall lining	Asbestos cement sheet	Non-friable	4 sqm	Good/Stable	Protect the retained ACM from damage during the course of the works
05/09/2017	Upstairs shower wall and ceiling lining	Asbestos cement sheet	Non-friable	15 sqm	Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works