

# ASBESTOS REGISTER

**SITE:** 7803 Siegloff 34A Greville Street, Clovelly

**LAST UPDATED:** 27/06/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Type	Friable / Non-Friable	Quantity	Condition	Assessment / Action
02/02/2017	Gable end window awnings	Asbestos cement shingles	Non-friable	5 sqm (4.2 sqm actual)	Good/stable Painted	To be removed by Cape Cod as part of proposed Contract works 4.2 sqm removed 26/06/2017
26/06/2017	Gable end window awnings	Asbestos cement shingles	Non-friable	4.2 sqm	Good/stable Painted	4.2 sqm removed 26/06/2017
02/02/2017	Rear patio – infill panel above retaining wall and wall common with store	Asbestos cement sheet	Non-friable	8.5 sqm	Good/stable Painted	To be removed by Cape Cod as part of proposed Contract works
02/02/2017	Kitchen – walls common with laundry and bedroom 3	Asbestos cement sheet	Non-friable	4.5 sqm	Good/stable Painted	To be removed by Cape Cod as part of proposed Contract works
02/02/2017	Bedroom 3 wall linings	Asbestos cement sheet	Non-friable	7 sqm	Good/stable Painted	To be removed by Cape Cod as part of proposed Contract works

## ASBESTOS REGISTER

02/02/2017	Store wall linings	Asbestos cement sheet	Non-friable	13.5 sqm	Good/stable Painted	To be removed by Cape Cod as part of proposed Contract works
02/02/2017	Laundry wall linings	Asbestos cement sheet	Non-friable	10 sqm	Good/stable Painted	To be removed by Cape Cod as part of proposed Contract works
02/02/2017	Shower wall and ceiling lining	Asbestos cement sheet	Non-friable	13.75 sqm	Good/stable Painted	To be removed by Cape Cod as part of proposed Contract works
02/02/2017	Garage wall, ceiling lining and gable ends	Asbestos cement sheet	Non-friable	34.5 sqm	Good/stable Painted	To be removed by Cape Cod as part of proposed Contract works
02/02/2017	Electrical meter board	Asbestos cement sheet cladding	Non-friable	1 sqm	Good/stable Some dust in the bottom of meter box	Protect the retained ACM from damage during the course of the works