

# ASBESTOS REGISTER

**SITE:** 7809 Sato 68 Catalpa Crescent, Turrumurra

**LAST UPDATED:** 01/03/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Type	Friable / Non-Friable	Quantity	Condition	Assessment / Action
21/12/2016	Eave soffit lining	Asbestos cement sheet	Non-friable	2.5 sqm	Good/stable	Remove and dispose of the ACM as part of the contract works
21/12/2016	Gable end lining	Asbestos cement sheet	Non-friable	4.5 sqm	Good/stable	Remove and dispose of the ACM as part of the contract works
21/12/2016	Front porch	Asbestos cement sheet	Non-friable	1 sqm	Good/stable	Remove and dispose of the ACM as part of the contract works
21/12/2016	Rear deck pergola	Asbestos cement weatherboard trim	Non-friable	Unknown	Good/stable	Protect and retain the ACM from damage during the course of the works
21/12/2016	Laundry	Asbestos cement sheet to wall linings	Non-friable	Unknown	Good/stable	Protect and retain the ACM from damage during the course of the works
21/12/2016	Shed	Asbestos cement weatherboard cladding	Non-friable	Unknown	Good/stable	Protect and retain the ACM from damage during the course of the works