

ASBESTOS REGISTER

SITE: 7895 Albrecht 17 Karrabul Road, St Helens Park

LAST UPDATED: 04/12/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Type	Friable / Non-Friable	Quantity	Condition	Assessment / Action
28/11/2017	Eave soffit lining	Asbestos cement sheet	Non-friable	28 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
28/11/2017	Porch soffit lining	Asbestos cement sheet	Non-friable	4 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
28/11/2017	Ensuite wall lining	Asbestos cement sheet	Non-friable	18 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
28/11/2017	Laundry wall lining	Asbestos cement sheet	Non-friable	14.5 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
28/11/2017	Bathroom wall lining	Asbestos cement sheet	Non-friable	14.5 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works

ASBESTOS REGISTER

28/11/2017	WC wall lining	Asbestos cement sheet	Non-friable	6 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
28/11/2017	Garage infill above roller door	Asbestos cement sheet	Non-friable	1.5 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
28/11/2017	Electrical meter board	ACM	Non-friable	0.5 sqm	Good/Stable	Protect the retained ACM from damage during the course of the works