

ASBESTOS REGISTER

SITE: 7856 Cardew.Lemon 15 Haldane Crescent, Lane Cove

LAST UPDATED: 19/09/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Type	Friable / Non-Friable	Quantity	Condition	Assessment / Action
18/07/2017	Eave soffit lining	Asbestos cement sheet	Non-friable	9 sqm	Broken and damaged to north western elevation eaves	4.5 sqm to be removed by Cape Cod as part of the contract works. Protect the retained ACM from damage during the course of the works 4.5 sqm removed 18/09/2017
18/07/2017	Gable end cladding	Asbestos cement sheet	Non-friable	27.5 sqm	Good/Stable Surface coated to the exposed area	23 sqm to be removed by Cape Cod as part of the contract works. Protect the retained ACM from damage during the course of the works 23 sqm removed 18/09/2017
18/07/2017	Front spandrel panels under windows	Asbestos cement sheet	Non-friable	1 sqm	Good/Stable Surface coated to the exposed area	Protect the retained ACM from damage during the course of the works

ASBESTOS REGISTER

18/07/2017	Front porch soffit lining	Asbestos cement sheet	Non-friable	7 sqm	Good/Stable Surface coated to the exposed area	Protect the retained ACM from damage during the course of the works
18/07/2017	Boundary fence/neighbouring shed	Asbestos cement sheet	Non-friable	7 sqm	Good/Stable Surface coated to the exposed area	Protect the retained ACM from damage during the course of the works
18/07/2017	Study/workshop ceiling lining	Asbestos cement sheet	Non-friable	12 sqm	Good/Stable Surface coated to the exposed area	Protect the retained ACM from damage during the course of the works
18/07/2017	Disused ceiling mounted hot water system	ACM	Non-friable	Unknown	Unknown	Remove and dispose of the ACM as part of the contract works
18/07/2017	Under floor space	Asbestos cement sheet	Non-friable	Unknown	Broken pieces Damaged	Remove and dispose of the ACM as part of the contract works