

# ASBESTOS REGISTER

**SITE:** 7745 Ighodaro 50 Eileen Street, North Balgowlah

**LAST UPDATED:** 27/03/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Type	Friable / Non-Friable	Quantity	Condition	Assessment / Action
09/06/2016	Eave soffit lining	Asbestos cement sheet	Non-friable	Unknown	Good/stable	Protect and retain ACM from damage during the course of the works
09/06/2016	Shower	Asbestos cement wall lining	Non-friable	Unknown	Good/stable	Protect and retain ACM from damage during the course of the works
09/06/2016	Electrical meter board	Asbestos cement sheet	Non-friable	Unknown	Good/stable	Protect and retain ACM from damage during the course of the works
09/06/2016	Carport	Asbestos cement ceiling lining	Non-friable	Unknown	Good/stable	Protect and retain ACM from damage during the course of the works