

# ASBESTOS REGISTER

**SITE:** 7829 Zheng.Li 12 Bell Street, Maroubra

**LAST UPDATED:** 31/07/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Type	Friable / Non-Friable	Quantity	Condition	Assessment / Action
27/07/2017	Eave soffit lining	Asbestos cement sheet	Non-friable	25.5 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
27/07/2017	Laundry & WC ceiling lining	Asbestos cement sheet	Non-friable	5 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
27/07/2017	Ensuite wall lining	Asbestos cement sheet	Non-friable	6 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
27/07/2017	Rear balcony awning	Asbestos cement sheet	Non-friable	1 sqm	Good/Stable Surface coated to the exposed areas	To be removed by Cape Cod as part of the contract works
27/07/2017	External infill panel above sunroom window	Asbestos cement sheet	Non-friable	1 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works

## ASBESTOS REGISTER

27/07/2017	Study spandrel panel and bay window soffit lining	Asbestos cement sheet	Non-friable	3 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
27/07/2017	Shed	Asbestos cement sheet cladding	Non-friable	24 sqm	Some broken sheets/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works