

ASBESTOS REGISTER

SITE: 7874 Alcorn.Mitchell 2 Shaw Avenue, Kingsford

LAST UPDATED: 20/11/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Type	Friable / Non-Friable	Quantity	Condition	Assessment / Action
14/11/2017	Eave soffit lining	Asbestos cement sheet	Non-friable	14 sqm	Good/Stable Surface coated to the exposed areas	5 sqm to be removed by Cape Cod as part of the contract works. Protect the retained ACM from damage during the course of the works
14/11/2017	Eave soffit lining	Asbestos cement sheet	Non-friable	9 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
14/11/2017	Gable end cladding under weatherboard cladding	Asbestos cement sheet	Non-friable	8.5 sqm	Good/Stable Surface coated to the exposed areas	To be removed by Cape Cod as part of the contract works
14/11/2017	Workshop ceiling lining	Asbestos cement sheet	Non-friable	19.5 sqm	Good/Stable Surface coated to the exposed areas	To be removed by Cape Cod as part of the contract works

ASBESTOS REGISTER

14/11/2017	Laundry ceiling lining	Asbestos cement sheet	Non-friable	8 sqm	Good/Stable Surface coated to the exposed areas	To be removed by Cape Cod as part of the contract works
14/11/2017	Pool pump area ceiling lining	Asbestos cement sheet	Non-friable	3.5 sqm	Good/Stable Surface coated to the exposed areas	To be removed by Cape Cod as part of the contract works
14/11/2017	Garage infill panel under weatherboard cladding	Asbestos cement sheet	Non-friable	3 sqm	Good/Stable Exposed to the back side of sheet	Protect the retained ACM from damage during the course of the works