

# ASBESTOS REGISTER

**SITE:** 7787 Gordon 19 Yethonga Avenue, Lane Cove West

**LAST UPDATED:** 21/03/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Type	Friable / Non-Friable	Quantity	Condition	Assessment / Action
12/01/2017	Eave soffit lining	Asbestos cement sheet	Non-friable	0.5 sqm	Good/stable Painted	Protect the retained ACM from damage during the course of the works
12/01/2017	Carport ceiling lining	Asbestos cement sheet	Non-friable	16 sqm	Good/stable Painted	Protect the retained ACM from damage during the course of the works
12/01/2017	Cathedral ceiling ends in bedroom 1 and lounge room	Asbestos cement sheet	Non-friable	16 sqm	Good/stable Painted	Protect the retained ACM from damage during the course of the works
12/01/2017	Front yard (adjacent to electrical meter board)	Asbestos cement sheet	Non-friable	2.9 sqm	Good/stable Full sheet	Remove and dispose of the ACM