

# ASBESTOS REGISTER

**SITE:** 7791 Rock 52 Donovan Avenue, Maroubra

**LAST UPDATED:** 23/02/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Type	Friable / Non-Friable	Quantity	Condition	Assessment / Action
01/02/2017	Eave soffit lining	Asbestos cement sheet	Non-friable	32.5sqm	Good/stable Painted	Protect the retained ACM from damage during the course of the works
01/02/2017	Under floor space (just inside front access hatch)	Asbestos cement sheet	Non-friable	Unknown	Broken pieces/damaged	Remove and dispose of the possible ACM
01/02/2017	Electrical meter box front door	Asbestos cement sheet	Non-friable	0.25sqm	Good/stable Painted	Protect the retained ACM from damage during the course of the works