

3D Printing

In the Chemistry Instrument Shop

Blaise Thompson

University of Wisconsin–Madison

October 25, 2023



- ▶ can be cheap
- ▶ slow (wall time)
- ▶ fast (human time)



Introduction

Stratasys

Design

Conclusion

- ▶ stereolithography (SLA)
- ▶ selective laser sintering (SLS)
- ▶ fused deposition modeling (FDM)



UPrint SE Plus

- ▶ only one material: ABS
- ▶ soluble support (proprietary)
- ▶ build plates
- ▶ temperature controlled environment
- ▶ layer thickness 10 thousandths of an inch
- ▶ minimum wall thickness 36 thousandths of an inch
- ▶ build volume 8"x8"x6"



Acrylonitrile butadiene styrene


- ▶ glass transition 105 C
- ▶ poor chemical compatibility with organic solvents
- ▶ \$3 per cubic inch




CAD DESIGN TIPS FOR 3D PRINTING

BY BILLIE RUBEN






Make walls a multiple of your extrusion line width for a smooth slice. If it was 0.4mm use 0.8, 1.2, 1.6, etc.




Filament must be laid upon existing material, so avoid steep overhangs to reduce the need for support.




Vertical holes are fine, but horizontal ones should be tear-drop shaped to mitigate steep overhangs.






A slit, bolt and trapped nut
can be added to holes to
allow them to be tightened
around another part.



Adding a fillet or chamfer between a wall and base strengthens the join by adding more interface.




Due to the planar layering of most 3D printers, print orientation has a significant impact on strength.


Introduction

Stratasys

Design

Conclusion





OpenScad



Thanks for your attention!

