






















































26 	OUI	0048SRB6  (RAC.ETH.1GE) 1GE/1 CHERBG VDSX28/CMNCHE-CHERBG PT6298/GVDS     		08/09/2021	
27 	OUI	0048ZZH1  (RAC.ETH.10GE) 10GE/1 CHERBG TOUX09/ITITLV- CHERBG OCT/OCTE     		10/02/2021	
28 	OUI				
29 	OUI	0044ZWW4  (RAC.ETH.1GE) 1GE/1 CHERBG 1LECLE/CCMTOU-CHERBG PT6298/GVDS     		17/12/2019	
30 	OUI	0045ABZ0  (RAC.ETH.1GE) 1GE/2 CHERBG 1LECLE/CCMTOU-CHERBG PT6298/GVDS     		17/12/2019	
31 	OUI	0055UDV4  (RAC.ETH.1GE) 1GE/1 CHERBG PT6298/GVDS- CHERBG LUMIER/CEHOSP     		15/04/2024	
32 	OUI				
33 	OUI				
34 	OUI				
35 	OUI	0058VME2  (RAC.ETH.1GE) 1GE/1 CHERBG BOIS0A/CFA- CHERBG PT6298/GVDS     		02/10/2025	
36 	OUI	0052RKY5  (RAC.ETH.10GE) 10GE/1 CHERBG KOENIN/ORCHNE-CHERBG OCT/OCTE     		25/08/2022	

Lorsque j'ai réalisé mon étude, j'ai repéré que la fibre numéro 35 était libre, tout comme la numéro 34 sur cette image. Aujourd'hui, les travaux sont terminés, il est donc normal de voir une prestation associée à cette fibre (0058VME2).

Paire Occupée par CLP : ● OUI ● NON

OUI : Média physique occupé par une CLP, NON : Média physique non occupé par une CLP.