




Section Through Old Beam





FLASHING DIVERTING WATER FROM DECK LEDGER (1 OF 2)