

Fire Safety Inspection Report

Fire Safety Inspection Report

Building Name: Antilia Apartment

Inspection Date: 2024-09-03

Inspector Name: Vipul Patil

1. Inspection Summary

This inspection was conducted on 2024-09-03 at Antilia Apartment. While fire extinguishers were present,

2. Detailed Findings

- Fire Extinguishers:
 - Present: Yes
 - Condition: Expired
 - Comments: All fire extinguishers present were found to be expired. This poses a significant risk as
- Fire Alarm System:
 - Condition: Not Present
 - Comments: No fire alarm system was found in the building. This is a major safety concern as a fire
- Exits:
 - Number: 3
 - Condition: Not assessed (requires further investigation)
 - Comments: The number of exits was noted, but the condition of these exits (e.g., clear, unobstructed)

3. Risk Assessment

The lack of a functional fire alarm system and expired fire extinguishers presents a high risk to the occupants.

4. Next Steps

- Immediate Action: The building management must immediately replace all expired fire extinguishers with
- Installation of Fire Alarm System: A fully functional fire alarm system, including smoke detectors and
- Exit Condition Assessment: A thorough assessment of the existing exits should be conducted to ensure
- Fire Safety Training: The building management should schedule fire safety training for all occupants to

Recommendation:

Fire Safety Inspection Report

The building management should take immediate action to address the identified deficiencies and ensu