

Fire Safety Inspection Report

Fire Safety Inspection Report

Building Name: GOKULDAM SOCIETY

Inspection Date: 2024-10-04

Inspector Name: CHALU PANDEY

1. Inspection Summary

This inspection was conducted on October 4, 2024, at GOKULDAM SOCIETY. The inspection re

2. Detailed Findings

- Fire Extinguishers:
 - Ground floor: No fire extinguishers were found.
 - 2nd floor: Expired fire extinguishers were found.
- Fire Alarm System:
 - The fire alarm system was operational and all components were functioning correctly.
- Exits:
 - The building's exits were in satisfactory condition, providing adequate escape routes in case

3. Risk Assessment

The lack of functioning fire extinguishers poses a significant risk to the occupants of GOKULDAM

4. Next Steps

- Immediate Action:
 - The building management must immediately procure and install functioning fire extinguishers
 - Expired fire extinguishers on the 2nd floor must be replaced with new, functional ones.
- Long-Term Recommendations:
 - Implement a regular fire safety inspection schedule, including checks on fire extinguishers, fir
 - Provide fire safety training for building occupants, covering the use of fire extinguishers and e
 - Review and update the building's fire safety plan to ensure it is comprehensive and aligned w

Note: This report is intended to highlight fire safety concerns and provide recommendations for in