

# Fire Safety Inspection Report

## Fire Safety Inspection Report

Building Name: GOKULDAM SOCIETY

Inspection Date: 2024-10-04

Inspector Name: CHALU PANDEY

### 1. Inspection Summary

This inspection was conducted on October 4, 2024, at GOKULDAM SOCIETY. While the fire alarm

### 2. Detailed Findings

#### Fire Extinguishers:

- Presence: No fire extinguishers found on the ground floor. Expired fire extinguishers found on the 2nd floor.
- Condition: Expired extinguishers are not considered functional and are a safety hazard.
- Recommendations:
  - Immediately procure and install fire extinguishers on the ground floor, ensuring they are accessible.
  - Replace the expired fire extinguishers on the 2nd floor with new and functional ones.
  - Conduct regular inspections and maintenance of all fire extinguishers to ensure their functionality.

#### Fire Alarm System:

- Condition: Functional.
- Recommendations:
  - Continue regular testing and maintenance of the fire alarm system to ensure its continued functionality.
  - Ensure all occupants are familiar with the fire alarm system and evacuation procedures.

#### Exits:

- Condition: The condition of the exits was assessed and rated as "5" (acceptable).
- Recommendations:
  - Ensure exits are kept clear of obstructions at all times.
  - Conduct regular inspections of exits to ensure they are readily accessible and functional.

### 3. Risk Assessment