

Fire Safety Inspection Report

Fire Safety Inspection Report

Building Name: Eiffel Tower

Inspection Date: 2024-09-11

Inspector Name: Manish Sonawane

1. Inspection Summary

This inspection of the Eiffel Tower revealed significant fire safety deficiencies. The building lacks

2. Detailed Findings

* **Fire Extinguishers:** No fire extinguishers were present.

* **Fire Alarm:** The fire alarm system was non-functional and not present.

* **Exits:** The building had two exits. However, the number of exits is insufficient for the size and

3. Risk Assessment

The absence of fire extinguishers and a functional fire alarm system creates a significant risk to life

4. Next Steps

Immediate Actions:

* **Install fire extinguishers:** The building must be equipped with a sufficient number of fire exting

* **Install a functional fire alarm system:** A fully operational fire alarm system, including smoke c

* **Increase the number of exits:** The building requires a greater number of exits to facilitate sa

Long-Term Actions:

* **Develop a comprehensive fire safety plan:** A detailed fire safety plan should be developed, c

* **Conduct regular fire drills:** Regular fire drills should be conducted to ensure occupants are fa

* **Train staff on fire safety:** Building staff should receive comprehensive training on fire safety p

Note: This report highlights critical fire safety deficiencies. Urgent action is required to address