

# Fire Safety Inspection Report

## Fire Safety Inspection Report

Building Name: omniwas apartment

Inspection Date: 2023-02-13

Inspector Name: CHALU PANDEY

### 1. Inspection Summary

This inspection revealed significant fire safety deficiencies at omniwas apartment. The building la

### 2. Detailed Findings

- Fire Extinguishers:
  - No functional fire extinguishers were found.
  - While some extinguishers were present, they were not properly pressurized and therefore no
  - Comment: The lack of functional fire extinguishers poses a major risk in the event of a fire, a
- Fire Alarm System:
  - The fire alarm system is currently non-functional.
  - Comment: A non-functional fire alarm system significantly hinders the ability to alert occupan
- Exits:
  - The number of exits was listed as "3", but no information was provided regarding their conditi
  - Comment: A comprehensive assessment of the condition and accessibility of all exits is critic

### 3. Risk Assessment

The absence of functional fire extinguishers and a non-functional fire alarm system creates a high

### 4. Next Steps

The following actions are urgently required to address the identified fire safety deficiencies:

- Immediate Action:
  - Fire Extinguishers: Ensure all fire extinguishers are properly charged and maintained. Repla
  - Fire Alarm System: Immediately repair and restore the fire alarm system to full functionality.
- Within 30 Days:
  - Exits: Conduct a thorough inspection of all exits to ensure they are in good condition, clearly