

Fire Safety Inspection Report

Fire Safety Inspection Report

Building Name: GOKULDAM SOCIETY

Inspection Date: 2024-10-04

Inspector Name: CHALU PANDEY

1. Inspection Summary

This report details the findings of a fire safety inspection conducted at GOKULDAM SOCIETY on

2. Detailed Findings

Fire Extinguishers

- Presence: No fire extinguishers were found on the ground floor.
- Condition: Expired fire extinguishers were found on the second floor.
- Comments: The absence of fire extinguishers on the ground floor and the presence of expired e

Fire Alarm System

- Condition: Functional
- Comments: The fire alarm system is currently operational and appears to be in good working or

Exits

- Overall Condition: Rated as 5 (Excellent).
- Comments: The exits appear to be clear and well-maintained, providing adequate access for e

3. Risk Assessment

High Risk:

- Lack of Fire Extinguishers: The absence of fire extinguishers on the ground floor poses a signif
- Expired Fire Extinguishers: Expired fire extinguishers are ineffective and potentially dangerous

Moderate Risk: