

# Fire Safety Inspection Report

## Fire Safety Inspection Report

Building Name: Omniwas

Inspection Date: 2024-09-23

Inspector Name: BOZYA

### 1. Inspection Summary:

This inspection revealed significant fire safety deficiencies at Omniwas. The building lacks fire ex

### 2. Detailed Findings:

- Fire Extinguishers:

- Present: No
- Condition: Not applicable
- Comments: The absence of fire extinguishers is a major fire safety hazard. Properly maintain

- Fire Alarm System:

- Condition: Partially Functional
- Comments: While some alarms were functional, others were not. A fully operational fire alarm

- Exits:

- Condition: 4 (Good)
- Comments: Exits were clear and accessible, indicating good maintenance.

### 3. Risk Assessment:

- High Risk: The absence of fire extinguishers poses a significant risk to the safety of occupants i
- Moderate Risk: The partially functional fire alarm system may delay evacuation, increasing the r
- Low Risk: The condition of the exits is satisfactory.

### 4. Next Steps:

- Immediate Action:

- Install fire extinguishers: The building must immediately install fire extinguishers in accordan
- Repair fire alarm system: The faulty fire alarm system must be repaired promptly by a qualifie

- Long-Term Action:

- Develop Fire Safety Plan: Implement a comprehensive fire safety plan that includes fire drills