

Fire Safety Inspection Report

Fire Safety Inspection Report

Building Name: dfsdc

Inspection Date: 2024-09-07

Inspector Name: accasc

1. Inspection Summary

This inspection identified a potential fire safety hazard related to the fire alarm system in the third

2. Detailed Findings

- Fire extinguishers present: Yes
- Fire alarm condition: Functional (except on the third floor)
- Overall condition of exits: 5 (This rating requires further explanation - please provide details about the condition of exits)
- Comments on fire extinguishers: yes present no issues
- Comments on fire alarms: its not present at third floor

3. Risk Assessment

The lack of a functional fire alarm system on the third floor constitutes a significant fire safety hazard.

4. Next Steps

- Immediate Action: The building management should immediately contact a qualified fire alarm technician to install a functional fire alarm system on the third floor.
- Follow-Up: A follow-up inspection should be scheduled within one week of the installation of the fire alarm system to ensure it is functioning correctly.
- Documentation: The building management should maintain records of all fire safety inspections and actions taken.

Note: The overall condition of exits rating requires further clarification. Please provide details about the condition of exits.