

Fire Safety Inspection Report

Fire Safety Inspection Report

Building Name: GOKULDAM SOCIETY

Inspection Date: 2024-10-02

Inspector Name: CHALU PANDEY

1. Inspection Summary

This inspection identified significant fire safety deficiencies within GOKULDAM SOCIETY. While

2. Detailed Findings

Fire Extinguishers:

- Presence: Yes
- Condition: Expired and not properly pressurized.
- Comments: The lack of proper pressure and expired status render the extinguishers ineffective

Fire Alarm System:

- Condition: Functional
- Comments: The fire alarm system is not present in emergency situations, rendering it ineffective

Exits:

- Number: 3
- Overall Condition: No information provided.

3. Risk Assessment

The identified deficiencies present a high risk of serious injury or death in the event of a fire.

- Expired and Improperly Pressurized Fire Extinguishers: These extinguishers are ineffective and
- Fire Alarm System Not Present in Emergencies: The lack of a functional alarm system during a

4. Next Steps